



298339

DRAFT



Crawford Station – Parcel O
Date: July 3, 2007

Description:
View looking south. Hand digging soil over an exposed 6-inch diameter pipe located west of the south purifier box.



Crawford Station – Parcel O
Date: July 3, 2007

Description:
View looking south of two parallel concrete walls. The concrete wall on the left side of the photo is the western end of the south purifier box. The wall on the right is of an unknown structure.

DRAFT



Crawford Station – Parcel O
Date: July 3, 2007

Description:
View to the south of the concrete footer used to support the western wall of the south purifier box. The top of the footer was located approximately 9 feet below ground surface.



Crawford Station – Parcel O
Date: July 3, 2007

Description:
Exposed concrete footer west of the south purifier box. View looking east.

DRAFT



Crawford Station –
Parcel O
Date: July 3, 2007

Description:
Excavating inside
western end of south
purifier box. View
looking south.



Crawford Station –
Parcel O
Date: July 3, 2007

Southwestern corner of
south purifier box looking
north. Inside wall of south
purifier box covered with
a steel plate.

DRAFT



Crawford Station –
Parcel O
Date: July 3, 2007

Description:
Top of concrete wall
located approximately 7-
feet south of the southern
wall of the south purifier
box. View looking east.
This wall appears to
parallel the southern wall
of the south purifier box.



Crawford Station –
Parcel O
Date: July 3, 2007

Description:
Southwestern corner of the
north purifier box. View
looking east.

DRAFT



Crawford Station –
Parcel O
Date: July 3, 2007

Description:
View to the east of the
north and south purifier
boxes. A concrete wall
connecting the western
ends of the boxes is visible
in the lower right corner of
the photo.



Crawford Station –
Parcel O
Date: July 3, 2007

Description:
Western ends of the
purifier boxes looking
northeast. Auger used to
drill the ComEd tower
foundation is visible in
upper portion of the photo.

DRAFT



Crawford Station –
Parcel O
Date: July 3, 2007

Description:
Western ends of the
purifier boxes looking to
the west. The concrete
wall connecting the
purifier boxes is located in
the center of the photo.



Crawford Station –
Parcel O
Date: July 3, 2007

Description:
Backfilling excavation
looking southwest.